

ATTENTION:

GENERAL MANAGER
 PARTS MANAGER
 CLAIMS PERSONNEL
 SERVICE MANAGER

IMPORTANT - All
 Service Personnel
 Should Read and
 Initial in the boxes
 provided, right.



SUBARU®

QUALITY DRIVEN® SERVICE

SERVICE BULLETIN

APPLICABILITY: 2005 Impreza, Legacy, and Forester

NUMBER: 18-116-07

DATE: 03/16/07

SUBJECT: Service Manual Corrections

INTRODUCTION

The purpose of this bulletin is to provide a description of current changes to Service Manuals available via the Subaru Technical Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will **not** be made available to update printed Service Manuals.

Paper manuals may have different page numbering then what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STIS web site for all future, updated service manual information.

YEAR	MODEL	BOOK/ VOL#	MSA#	SECTION	PAGE(S)	DESCRIPTION OF CHANGE
2005	Legacy	2	MSA5T0501A	Engine (H4SO)	EN(H4SO)(diag)- 243	Diagnostic step 2 has changed for DTC P1443
		3	MSA5T0502A	Engine (H4SO U5)	EN(H4SO U5)(diag)-286	Diagnostic step 2 has changed for DTC P1443
		4	MSA5T0503A	Engine (H4DOTC)	EN(H4DOTC)(diag)- 245	Diagnostic step 2 has changed for DTC P1443
		5	MSA5T0504A	Engine (H6DO)	EN(H6DO)(diag)- 290	Diagnostic step 2 has changed for DTC P1443
		7	MSA5T0506A	Chassis	FS - 2	Rear Toe-In Specifications added
					FS - 11	Rear Toe-In Specifications added
		8	MSA5T0507A	Body	WW - 18	Rear Wiper Motor testing corrected
		9	MSA5T0808A	Wiring System	WI - 38,50	New Wiring Diagrams
					WI - 158	New Diagram for Rear Wiper System
WI - 216	Connector Chart for Rear Harness modified					
WI - 217	New Diagram for Rear Harness					
2005	Forester	2	MSA5T0521A	Engine (H4SO)	EN(H4SO)(diag)- 278	Diagnostic step 2 has changed for DTC P1443
		3	MSA5T0522A	Engine (H4DOTC)	EN(H4DOTC)(diag)- 294	Diagnostic step 2 has changed for DTC P1443

YEAR	MODEL	BOOK/ VOL#	MSA#	SECTION	PAGE(S)	DESCRIPTION OF CHANGE
2005	Impreza	2	MSA5T0511A	Engine (H4SO)	EN(H4SO)(diag)-264	Diagnostic step 2 has changed for DTC P1443
					EN(H4SO)(diag)-293	Check value for diagnostic step 18 is corrected for DTC 2101
					EN(H4SO)(diag)-314	Check value for diagnostic step 13 is corrected for DTC 2135
		3	MSA5T0512A	Engine (H4DOTC)	EN(H4DOTC)(diag)-290	Diagnostic step 2 has changed for DTC P1443
		4	MSA5T0513A	Engine Sti	EN(STi)(diag)-275	Diagnostic step 2 has changed for DTC P1443
					EN(STi)(diag)-332	Check value for diagnostic step 18 is corrected for DTC 2101
EN(STi)(diag)-356	Check value for diagnostic step 13 is corrected for DTC 2135					